

TEST REPORT

 Report No.:
 HC60112/2023

 Page:
 1
 of
 12

 Date:
 July 7, 2023
 12

VECOW CO., LTD. 3F., NO.10, JIANKANG RD., ZHONGHE DIST., NEW TAIPEI CITY, TAIWAN

The following merchandise was submitted and identified by the vendor as:Product Description:Expandable Fanless Embedded SystemStyle/ Item No.:ECX-3200/ No.1Quantity:Total 1 pieceTesting Period:Jun. 16, 2023 to Jun. 30, 2023Note:(Client's declaration) The configuration of specimen(s) as shown below:1.CPU: 12th Gen Intel® CoreTM i7-12700 TE @1.40GHz

- 2. RAM: Gold key (Neo Forza) DDR5 4800 NON-ECC SODIMM 32GB x 2
- 3. SSD: Innodisk 2.5" SATA SSD 3ME4 128GB

We have tested the submitted sample(s) as requested and the following results were obtained:

<u>Test Required:</u> (According to client's test specification, please see following sheets in detail.)

1. Low Temperature Test

- 2. High Temperature and High Humidity Test
- 3. Random Vibration Test
- 4. Mechanical Shock Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

Signed for and on behalf of SGS TAIWAN Ltd.

Alex Chen Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions of Electronic Documents at <u>www.sqs.com/en/terms-and-conditions</u> is information and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document perioduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unawful and offenders may be prosecuted to the fullest extent of the law.

> <mark>SGS Taiwan Ltd.</mark> 台灣檢驗科技股份有限公司_

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC60112/2023		23
Page:	2	of	12

1. Low Temperature Test:				
Test Equipment:				
Name		Brand	Model	Serial No.
Programmable Temperature	& Humidity Chamber	Giant Force	GTH-1000-60-CP-AR-H	MAA1904-001
Lab Environmental Cond	itions:			
Ambient temperature:	<u>(25 ± 3) °C</u>			
Ambient humidity:	<u>(55 ± 20) % RH</u>			
Test Location:	No. 31, Wu Chyuar	n Road, New 7	Taipei Industrial Park, Wu	Ku District, New
	Taipei City, Taiwan	<u>l</u>		
Test Method/ Specificatio	<u>n:</u>			
Test method:	IEC 60068-2-1 Edi	tion 6.0: 2007	and client's request	
Sample condition:	Operating			
Temperature:	<u>-40°C</u>			
Duration:	16 hours			

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then execute the test program "Burn-In Test" and "3D Mark" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/en/terms-and-conditions/terms-end-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.: HC		50112/20	23
Page:	3	of	12

Reliability Laboratory

Style/ Item No .:

ECX-3200/ No.1
Total 1 piece

Test Result:

Quantity:

Specimen:

Check Item Style/ Item No.	Appearance Check (visual check)	Functional Check
ECX-3200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC60112/2023		
Page:	4	of	12

2. High Temperature and High Humidity Test:

Test Equipment:				
Name		Brand	Model	Serial No.
Programmable Temperature	& Humidity Chamber	Giant Force	GTH-1000-60-CP-AR-H	MAA1904-001
Lab Environmental Cond	itions.			
Ambient temperature:	$(25 \pm 3) \circ C$			
Ambient humidity:	<u>(55 ± 20) % RH</u>			
Test Location:	No.31, Wu Chyuan	Road, New T	aipei Industrial Park, Wul	Ku District, New
	Taipei City, Taiwar	<u>1</u>		
Test Method/ Specificatio	<u>n:</u>			
Test method:	<u>IEC 60068-2-78 Ec</u>	dition 2.0: 201	2 and client's request	
Sample condition:	<u>Operating</u>			
Temperature:	<u>75°C</u>			
Test Humidity:	<u>95% RH</u>			
Duration:	16 hours			

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then execute the test program "Burn-In Test" and "3D Mark" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/en/terms-and-conditions/terms-end-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC60112/202		23
Page:	5	of	12

Specimen:

Style/ Item No .: Quantity:

ECX-3200/ No.1 Total 1 piece

Test Result:

Check Item Style/ Item No.	Appearance Check (visual check)	Functional Check
ECX-3200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC60112/2023			
Page:	6	of	12	

3. Random Vibration Test:

Test	EU	uı	рп	len	ι.
Toot	Ea		nn	- n	4.

Name	Brand	Model	Serial No.	
Vibration Test System	UNHOLTZ-DICKIE	SAI60-H560BAC/2/ST	474	
Controller	Dactron	LASER	7110357	
Control Accelerometer	PCB	353B34	LW213529	

Lab Environmental Conditions:

Ambient temperature:	(25 ± 3) °C
Ambient humidity:	<u>(55 ± 20) % RH</u>

Test Location:

No.31, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

Test Method/ Specification:

Test Method:	IEC 60068-2-64	4 Edition 2.1: 201	19 and client's	request
Wave form:	Random			
Frequency:	(<u>10 ~ 2000) Hz</u>			
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (g ² /Hz)	Right Slope (dB/Oct.)
	10	-	0.0020	0
	2000	0	0.0020	-
	⇒equivalent t	to 2.0 g _{rms}		
Direction:	X, Y, Z axes (as	show in photo 5	~ 7)	1 m
Test duration:	2 hours/ axis			

- Sample condition: Operating
- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then execute the test program "Burn-In Test" and "3D Mark" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-edocument. Attention is drawn to the limitation of liability, indemnification and jurisdiction any. The Company's sole responsibility is to its Client and this document does not exorerate parties to a transaction from exercising all their rights and obligations under the transaction of documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, for greery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC60112/2023		
Page:	7	of	12

Reliability Laboratory

Style/ Item No .:

ECX-3200/ No.1
Total 1 piece

Test Result:

Quantity:

Specimen:

Check Item Style/ Item No.	Appearance Check (visual check)	Functional Check
ECX-3200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC60112/2023		
Page:	8	of	12

Test Equipment:			
Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	95-115D	M17656
Data Acquisition & Analysis System	LANSMONT	TP4 8A-CH SML	1115-001
ICP Accelerometer	PCB	353M288	190564
Lab Environmental Conditi Ambient temperature:	$\frac{\text{ions:}}{(25\pm3)^{\circ}\text{C}}$		
Ambient humidity:	$(~55\pm20$) % RH		
Test Location:	No.31, Wu Chyuan Road, N	New Taipei Industrial Park, W	VuKu District,
	New Taipei City, Taiwan		
Test Method/ Specification	<u>:</u>		
Test Method:	IEC 60068-2-27 Edition 4.0): 2008 and client's request	
Pulse shape:	Half-sine		
Acceleration:	<u>50 g</u>		
Pulse duration:	<u>11 ms</u>		
Shock direction:	<u>6 faces ($\pm X$, $\pm Y$, $\pm Z$ axes, s</u>	ee photo 8 ~ 13)	
No. of shock:	3 shocks/ axis (total 18 sho	<u>cks)</u>	

- Sample condition: Operating
- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen then execute the test program "Burn-In Test" and "3D Mark" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.sgs.com.tw



TEST REPORT

Report No.:	HC60112/2023		
Page:	9	of	12

Specimen:

Style/ Item No .: Quantity:

ECX-3200/ No.1 Total 1 piece

Test Result:

Check Item Style/ Item No.	Appearance Check (visual check)	Functional Check
ECX-3200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.


Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC60112/2023		
Page:	10	of	12

Test Photos:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.


Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No .:	HC60112/2023		
Page:	11	of	12

Test Photos--Continued:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.


Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC60112/2023		
Page:	12	of	12

Test Photos--Continued:



The End of Test Report

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558